

Buildings identified for further research with the view to potentially listing on Schedule 5 of *Palerang Local Environmental Plan 2014*

Address	Title Info	Description	Recommendations
7 Butmaroo St	Lot 201 DP 530664	Double fronted Miners Cottage, unsympathetic windows which could be replaced	Undertake more detailed inspection and assessment and if appropriate, list.
25 Butmaroo St	Lot 2 Sec 10 DP 758183	Anglican Rectory, Georgian Revival in the style of Hardy Wilson.	Undertake more detailed inspection and assessment and if appropriate, list.
35 Butmaroo St	Lot B DP 159293	Double fronted Edwardian weatherboard, renovated and extended.	Undertake more detailed inspection and assessment and if appropriate, list.
50 Butmaroo St	Lot 4 Sec 22 DP 758183	1910s double fronted roughcast render. Minor unsympathetic alterations, average condition, could be restored	Undertake more detailed inspection and assessment and if appropriate, list.
52 Butmaroo St	Lot 5 Sec 22 DP 758183	1920s double fronted weatherboard, highly intact, average condition, could be restored	Undertake more detailed inspection and assessment and if appropriate, list.
54 Ellendon St	Lot 5 Sec 23 DP 758183	Double fronted Late Victorian weatherboard, excellently restored	Undertake more detailed inspection and assessment and if appropriate, list
84 Ellendon St	Lot 1 DP 78280	Double fronted Edwardian weatherboard, good condition, garden setting	Undertake more detailed inspection and assessment and if appropriate, list.
86 Ellendon St	Lot 1 DP 844570	Double fronted late Victorian	Undertake more detailed inspection and assessment and if appropriate, list.
24 Gibraltar St	Lot 23 DP 591333	Edwardian cottage	Undertake more detailed inspection and assessment and if appropriate, list
31 Gibraltar St	Lot 1 DP730708	Cottage. C 1900, intact facade	Undertake more detailed inspection and assessment and if appropriate, list.
32 Gibraltar St	Lot 32 DP 739088	Single fronted weatherboard shop, stone side wall, brick chimneys. Unsympathetic windows which could be changed.	Undertake more detailed inspection and assessment and if appropriate, list.
74 Gibraltar St	Lot 11 Sec 4 DP7581	Late Victorian Gothic Revival Style villa thought to have been built as an Anglican Rectory in 1875. Recently renovated.	Undertake more detailed inspection and assessment and if appropriate, list. Identified in <i>St Philip's Church Bungendore 1864-2014</i> by Sally Osborne Church History. Noted as still standing and built in 1875.
90 Gibraltar St	Lot 17 Sec 4 DP758183	Double fronted, rendered late 19 th century cottage with sympathetic rear additions	Undertake more detailed inspection and assessment and if appropriate, list.
126 Gibraltar St	Lot 1 DP1182822	Double fronted weatherboard cottage, brick chimneys, landscape setting	Undertake more detailed inspection and assessment and if appropriate, list.

Buildings identified for further research with the view to potentially listing on Schedule 5 of *Palerang Local Environmental Plan 2014*

Address	Title Info	Description	Recommendations
59 Majara St	Lot 11 Sec 22 DP 758183	Late Victorian weatherboard semis, very old timber fence, highly intact façade, poor condition	Undertake more detailed inspection and assessment and if appropriate, list.
81 Majara St	Lot 22 DP 774589	Double fronted Late Victorian weatherboard cottage with large rear additions. Intact façade with unusual inset front verandah, Currently being restored.	Undertake more detailed inspection and assessment and if appropriate, list.
4 Molonglo St	Lot 18 DP 1114646	Late Victorian, double fronted weatherboard, average condition	Undertake more detailed inspection and assessment and if appropriate, list.
30 Osborne St	Lot 51 DP 572216	Edwardian weatherboard cottage	Undertake more detailed inspection and assessment and if appropriate, list.
1 Rutledge St	Lot 1 DP 833234	Double fronted Edwardian weatherboard cottage	Undertake more detailed inspection and assessment and if appropriate, list.
100 Rutledge St	Lot 9 Sec 19 DP 758183	Weatherboard Miners cottage with later additions	Undertake more detailed inspection and assessment and if appropriate, list
3 Turallo Tce	Lot 1 DP 743866	Double fronted Edwardian weatherboard cottage	Undertake more detailed inspection and assessment and if appropriate, list